

Hardy K C Lok

SUN HOUSE, 20TH FLOOR, 90 CONNAUGHT ROAD C., HONG KONG.

TEL: 2545 8818 FAX: 2354 0910

22 June 2006

Report on Contaminated Mud in the Tamar Reclamation

I am a Chartered Engineer and have been in the engineering and construction industry for over 30 years.

I am also a Director of the Society for Protection of the Harbour.

I have just shown a "Report on Contaminated Mud in the Tamar Reclamation" prepared by Mr M K S Chu.

From my personal knowledge and experience, I support the contents of this Report.

According to my knowledge, the contaminated mud was not removed from the Tamar Naval Basin before the site was reclaimed. The result of this oversight is that it is inevitable that the contaminated mud is still lying under the Tamar Site and "represents a serious health hazard to future occupants of and visitors to any development thereon."

Accordingly, I agree with the conclusion in Paragraph 7 of the Report that "the contaminated mud must be removed before the Tamar Site can be safely developed and made fit for human occupation."



LOK Kung-Chin Hardy